

**Coemar SpA** - Socio unico 46042 Castel Goffredo (MN) Italy - Via Inghilterra, 2/a Tel. +39 0376 77521 / Fax +39 0376 780657-779889 www.coemar.com - info@coemar.com

## FIXTURE: iWash Led DATE: 15/06/2007 TITLE: Fan Kit for iWash Led FROM: info.design@coemar.com REF: Coemar internal communication no. 06/2006 Official Official

1 – Fan Kit for iWash Led	
ISSUE	If run continuously for more than 24 hours, there is a small possibility that the chips controlling Pan and Tilt will burn.
REASONS	The particular working conditions of the fixture cause the problem.
SOLUTION	To eliminate the issue, Coemar can provide, upon request, a cooling kit ( <i>KIT133</i> ).
AVAILABILITY	Starting from April 2006.

For more information, please contact info.design@coemar.com or service@coemar.com

This document is for Coemar internal use only, do not circulate or modify without Coemar permission

