

**Order your Spare Parts here -> <http://www.lichtboxx.com/index.php/cPath/158/language/en>
www.lightspares.com | ©MS Lichttechnik GmbH, Hirschstettner Strasse 19A, 1220-Vienna, Austria**

Spare Parts List of Martin Rush MH 6 Wash

50480504	Fast-locking buckle
50480565	POWERCON socket
50480566	POWERCON socket
50480570	Hall-element board D2
50480590	Lock ring
50480591	Rubber pad
50480592	Front lens
50480593	Frost filter
50480594	Press plate for lens
50480595	Motor plate
50480596	Rubber for motor
50480597	Guide for motor
50480598	Step motor
50480600	Light rod
50480602	Light board with cooling
50480676	Display for Multibeam 2
50480680	DMX board Multibeam 2
50480695	Backligh board for PAR 2
50480700	Arm cover MH 5
50480703	Tilt follower wheel for belt MH 5
50480705	Stepper motor MH 5 YOKE, tilt and Pan
50480706	Isolation pole MH 5 Yoke
50480707	Pan pos wheel MH 5 Yoke
50480708	Spring MH 5 Yoke
50480709	Tilt belt MH 5 Yoke
50480711	Limit switch MH 5 Yoke
50480713	Positioning board MH 5 Yoke Tilt
50480714	PAN belt MH 5 Yoke
50480715	Pan follower wheel assembly MH 5 Yoke
50480716	Base cover MH 5
50480718	Organic display glass MH 5
50480723	Fast-locking shim MH 5
50480724	Foot MH 5
50480796	PSU for PAR2 RGBW, PAR2 CT and MH5
50480869	Rubbergasket for PAR 2 fan
50480887	Frontplate MH 6
50480888	Mainboard MH 6
50480889	Snap ring MH 6
50480890	Front head cover MH 6
50480891	Silicone sleeve MH
50480892	LED driver board MH 6
50480893	rear head cover MH 6
50481046	Fan DC 1

**Order your Spare Parts here -> <http://www.lichtboxx.com/index.php/cPath/158/language/en>
www.lightspares.com | ©MS Lichttechnik GmbH, Hirschstettner Strasse 19A, 1220-Vienna, Austria**