

Order your Spare Parts online here -> [lightspares.com](https://lightspares.com) Worldwide Express Delivery  
Part or number not found? Send us a request! -> [Contact us!](#)

### Spare Parts List of ADB Warp M12-30 ©

39570	Accessory holding clip
1001.60.010	Glass reflector
1001.60.020	Lamphouse subassembly
1001.60.300	Input lens kit (complete assembly)
1001.60.305	Input lens kit (lens + screws)
1001.60.310	Output lens kit (complete assembly)
1001.60.315	Output lens kit (lens + screws)
1001.60.360	Teflon ring kit
1001.60.370	Diaphragm
1001.60.400	Sliding rail for input lens
1001.60.410	Sliding rail for output lens
1001.60.500	Front cassette
1001.60.510	Lens tube cover
1001.61.001	Lamp subassembly
1001.61.040	G9.5 lampholder kit with cable
1001.61.200	Wheel & ring subassembly 12°-30°
1001.61.340	Belt kit
1001.65.000	Top box front panel assembly
1001.65.010	24 V DC power supply
1001.65.200	Pan & Tilt motordriver + cooling kit
1001.65.210	Left motordriver + cooling kit
1001.65.220	Right motordriver + cooling kit
1001.65.230	Magnet sensor kit
1001.65.240	PCB lamp control kit
1001.65.260	Infra red sensor right kit
1001.65.270	Infra red sensor left kit
1001.65.280	XLR-4 pts kit
1001.65.290	Top box board kit
1001.65.300	Fuse kit
1001.65.660	Kit motor gear
1001.65.670	Kit pan belt
1001.65.680	Kit tilt belt
2990.40.500	G9.5 axial, biplane filament, halogen lamp 230V-800W-3200K-300h
2990.40.405	G9.5 axial, biplane filament, halogen lamp 230V-600W-3200K-300h
1092.10.600	Hook clamp for WARP/M
1000.40.100	Double gobo holder
1000.40.110	Combined iris diaphragm & gobo holder
1050.40.405	Color changer with adapter plate and XLR 4 cable
1050.40.400	Adapter plate with XLR 4 cable

