

**Order your Spare Parts here -> <http://www.lichtboxx.com/index.php/cPath/158/language/en>
www.lightspares.com | ©MS Lichttechnik GmbH, Hirschstettner Strasse 19A, 1220-Vienna, Austria**

Spare Parts List of Martin Rush Firber Source 1

17300020 Plastic adaptor for colorfilter
50480870 Screw for fiber sleeve
50480871 Fiber sleeve
50480872 Motor for color wheel
50480873 Motor for twinkel wheel
50480874 Sensorboard color and twinkel
50480875 Belt for Fibersource
50480876 Thermoswitch Fibersource
50480877 LED for Fibersource
50480878 PSU for RUSH Fibersource
50480879 DMX board for RUSH Fibersource
50480880 Fan RUSH Fibersource
50480881 Mainboard Fibersource
50480882 Driver board for Fibersource
50480883 DMX Isolation board
50480884 Fan net
50480885 DIPSWITCH board
50480886 Power cable for US with Powercon, RUSH

**Order your Spare Parts here -> <http://www.lichtboxx.com/index.php/cPath/158/language/en>
www.lightspares.com | ©MS Lichttechnik GmbH, Hirschstettner Strasse 19A, 1220-Vienna, Austria**